

Parts List CNC

(Dimension in mm)

#	Part	Material	pcs	L	W	T
1	Machine Bed	Plywood	1	530	815	15
2	Traverse Base	"	4	530	70	15
3	Sides (Y-Axis)	"	2	800	120	15
4	Motor Mounts	"	3	75	120	15
5	Traverse (X-Axis)	"	1	650	120	15
6	Traverse (Z-Axis)	"	1	300	120	15
7	Router Mount Plate	"	1	170	120	15
8	Gantry Sides	"	2	301	220	15
	Square Timbers	Beech	2	800	32	30
	"	"	2	650	32	30
	"	"	2	300	32	30